

REV.		BY	E.C.N.
D	2) P16 WAS P33 1) ADDED TERMINAL LOCATIONS	TAB	0611 04
	(3) ADDED P/N 36820000	LG	0509 03
C	(2) ADDED P/N 67001000, 67002000 & 67003000 (1) 81392001 repl. 80850001		
B	REMOVED P/N 81337100	TAB	0506 26
A	BOARDS 81337000 & 81337100 REVISED TO SHOW CIRCUIT	TAB	0410 02
REL	RELEASED TO PROD.	TAB	0304 07
E	REMOVED POWER REQUIREMENTS	TAB	1406 16

MATERIAL:

NO.	PART NO.	PART NAME	REQ.

ELKHART BRASS MFG. CO., INC.
ELKHART, INDIANA

SCORPION WIRING DIAGRAM
(NO STOW) ALL ELKHART CONTROLS

DRN BY	TAB	SCALE	NONE	DATE	01/28/03
CHKD BY	TAB	CAT. NO.	8294-04 8394-04	PART NO.	30194000

STANDARD TOLERANCE
3 PLACE DEC.= ±.010
4 PLACE DEC.= ±.005
ANGLES = ±0°30'0"

SDRC

REMOVE ALL BURRS AND SHARP CORNERS UNLESS OTHERWISE SPECIFIED
DO NOT SCALE PRINT